

Super-Welder Upright Weld Rip Test Failure Reduction Project

Have you seen this process in action?

It's not the best tool for every situation, but under the right circumstances, here's how it can bring significant savings!

\$ 1.08M in Savings after 10 Weeks!!

The Project...


The Problem: Client was having to rework/reweld 25% of a specific product, costing unnecessary labor and welder time for the rework, but also taking production time from the welder doing the rework. It was also resulting in late / missed deliveries.

The Approach...Planning for Success...

The Project: Putting together a cross-functional/level team, led by Engineering, Create a Charter, and apply Lean Six Sigma protocol (DMAIC), and key tools / methods to conduct a detailed RC/CA (Root Cause/Corrective Action) process.

The Lean Six Sigma DMAIC Method


DMAIC (Define, Measure, Analyze, Improve, Control) steps enable a comprehensive RC/CA process, and enables optimizing critical factor performance to achieve overall performance goals. A Project Plan (Gantt) is also essential to ensure the project stays on track coupled with a project charter assures the agreement between all stakeholders on what needs to be accomplished.




Characterize/Stratify the rip test failures by welder, material, current settings, date/time, operator, tip wear, etc., looking for relationships, trends and possible correlations

Time/Stamp	Clock Number	Part Number	Channel Heat Loss	Sideral Heat Loss	Machine #	Parts welded (Heat loss) of 26	Weld Count	Stage 1 (Heat loss) Sch 1	Stage 1 (Heat loss) Sch 2	Stage 2 (Heat loss) Sch 1	Stage 2 (Heat loss) Sch 2	Unwelded Count	Count of Welds	Failure Type	Weld QC Initial	Defective Weld QC Initial	#Rip path, number of welds recorded	Inspection	Remarks	Mainstream	Time/Stamp	
4/2/2023 10:14	83404	US84	60101550		A033	200	1145	77	77	80	16	AROW	AROW				95	48676	NO	4/2/2023 10:14		
5/2/2023 13:31	83404	US84	60101515		A030	400	2168	78	78	82	19	AROW	AROW				86	48676	NO	5/2/2023 13:31		
5/2/2023 14:24	83404	US84	60101504		A030	300	1870	86	86	82	19	TOP WELD	TOP WELD				100	48676	NO	5/2/2023 14:24		
5/2/2023 14:24	83404	US84	60101538		A028	200	8736	89	89	91	16	AROW	AROW					48678	NO	5/2/2023 14:24		
5/3/2023 6:35	83404	US84	60101538		A028	100	1835	76	76	76	19	MAX	MAX							NO	5/3/2023 6:35	
5/3/2023 8:32	83404	US84	60101560		A033	300	1800	73	73	81	19	AROW	AROW				86	48678	NO	5/3/2023 8:32		
5/3/2023 11:24	83404	US84	60101538		A030	300	6800	80	80	84	13	AROW	AROW				50	48678	NO	5/3/2023 11:24		
5/5/2023 9:12	83404	US84	60102574	83234790	A028	100	2341	82	82	86	34	AROW	AROW				37	48681	NO	5/5/2023 9:12		
5/5/2023 9:50	83404	US84	60101504		A030	300	1870	79	79	80	16	TOP WELD	TOP WELD				70	48682	NO	5/5/2023 9:50		
5/5/2023 11:42	83404	US84	60205927	2302205052	A028	200	1201	76	76	80	15	AROW	AROW				53	48680	NO	5/5/2023 11:42		
5/5/2023 13:59	83404	US84	60101572	83234790	A028	100	2261	81	81	84	13	AROW	AROW				50	48682	NO	5/5/2023 13:59		
5/8/2023 13:49	83404	US84	60101579	83234790	A033	100	5973	80	80	84	19	MAX	MAX				100	48686	NO	5/8/2023 13:49		
5/9/2023 9:26	83404	US84	60101622		A030	500	9448	77	77	81	18	MAX	TLC					48684	NO	5/9/2023 9:26		
5/9/2023 9:36	83404	US84	60101584	2302205052	A030	300	1870	87	87	87	0	MAX	MAX							NO	5/9/2023 9:36	
5/10/2023 6:05	83404	US84	60101592		A033	1	4020	76	76	80	17	MAX	MAX				78	48686	NO	5/10/2023 6:05		
5/10/2023 6:10	83404	US84	60101536		A030	25	1825	80	80	84	24	AROW	AROW				23	48670	NO	5/10/2023 6:10		
5/10/2023 10:50	83404	US84	60101504	2302205052	A030	300	1870	84	84	84	13	AROW	AROW							NO	5/10/2023 10:50	
5/10/2023 11:28	83404	US84	60101616	832340940	A028	500		83	83	87	20	AROW	AROW				71	48674	NO	5/10/2023 11:28		
5/10/2023 13:44	83404	US84	60101539		A030	70	1768	80	80	84	15	MAX	MAX							NO	5/10/2023 13:44	
5/10/2023 14:28	85739	US84	60101539		A030	602	1802	79	79	83	0	34	MAX	MAX							NO	5/10/2023 14:28
5/10/2023 15:37	85739	US84			A030	635	1900	79	79	82	0	21	MAX	MAX							YES	5/10/2023 15:37
5/10/2023 16:43	85739	US84	60101539		A030	70	1768	80	80	84	15	MAX	MAX								YES	5/10/2023 16:43
5/11/2023 10:17	86787	US84	60101545		A030	500	8967	78	78	81	8	TOP WELD	GF				32	48697	NO	5/11/2023 10:17		
5/11/2023 14:38	86787	US84	60101565	83234790	A030	700	13869	81	81	82	9	AROW	GF								NO	5/11/2023 14:38
5/12/2023 9:18	86787	US84	60101540		A030	1	4020	76	76	80	17	MAX	MAX								NO	5/12/2023 9:18
5/12/2023 9:53	86787	US84	60101655		A030	1	442	77	77	80	12	AROW	GF								NO	5/12/2023 9:53
5/15/2023 6:43	86787	US84	60101532	2302205052	A030	101	1850	77	77	81	17	AROW	GF				34	48696	NO	5/15/2023 6:43		
5/15/2023 7:14	86787	US84	60101532	2302205052	A030	104	2431	81	81	85	13	AROW	GF								NO	5/15/2023 7:14
5/15/2023 9:20	86787	US84	60101532	83230940	A030	300	3533	85	85	88	18	MAX	GF				75	48699	NO	5/15/2023 9:20		
5/16/2023 5:22	86787	US84	60101584		A030	1	4020	76	76	80	17	MAX	ALL STATE								NO	5/16/2023 5:22
5/17/2023 6:20	83404	US84	60102717		A030	100	1601	76	76	80	10	AROW	GF				139	48670	NO	5/17/2023 6:20		
5/17/2023 7:59	83404	US84	60101524	83234790	A028	200	2418	76	76	80	13	AROW+TOP	GF				27	48677	NO	5/17/2023 7:59		
5/21/2023 10:15	83404	US84	60101504	83234790	A030	300	1870	84	84	84	13	AROW	GF				78	48678	NO	5/21/2023 10:15		
5/17/2023 10:22	83404	US84	60103566	2302205051	A030	600	8352	79	79	86	5	TOP WELD	GF				25	48680	NO	5/17/2023 10:22		
5/17/2023 13:06	83404	US84	60101572	12843405	A030	600	13536	80	80	84	13	AROW	GF				135	48678	NO	5/17/2023 13:06		
5/22/2023 14:21	86787	US84	60103561		A028	2905	200	78	78	82	82	TOP WELD	GF				56	48683	NO	5/22/2023 14:21		
5/22/2023 14:36	85739	US84			A028	210	1325	78	78	81	0	8	AROW	GF							YES	5/22/2023 14:36
5/22/2023 17:55	86787	US84	60102700		A030	100	1601	76	76	80	10	AROW	GF				145	48680	NO	5/22/2023 17:55		
5/23/2023 6:45	86787	US84	60102697	83234790	A028	100	1500	76	76	80	7	AROW+TOP	TLC				96	48618	NO	5/23/2023 6:45		
5/24/2023 8:51	86787	US84	60102697		A030	100	2352	76	76	80	80	TOP WELD	TLC				119	48624	NO	5/24/2023 8:51		
5/24/2023 9:18	86787	US84	60102697		A030	100	2352	76	76	80	80	TOP WELD	TLC								NO	5/24/2023 9:18
5/24/2023 10:09	86787	US84	60102697		A028	225	3525	76	76	80	80	TOP WELD	TLC				187	48627	NO	5/24/2023 10:09		
5/24/2023 11:53	86787	US84	60102697	2302205052	A030	100	2352	76	76	80	80	TOP WELD	TLC				187	48627	NO	5/24/2023 11:53		
5/25/2023 19:18	86225	UP6	60102547	230220405	A030	100	13065	83	83	86	15	AROW	JC				210	48608	NO	5/25/2023 19:18		
5/25/2023 19:08	87491	72	60102546	230220405	A028	200	7961	78	78	78	0	AROW	JC								NO	5/25/2023 19:08
5/25/2023 19:08	87491	72	60102546	230220405	A028	200	7961	78	78	78	0	AROW	JC				102	48603	NO	5/25/2023 19:08		

From the team, identify CNX (Constants, Noise, Variables) sources for variation, determine priority to dive deeper, see if any are JDI (just do it) or require more analysis



Material Issues, and calculating CE (Carbon Equivalent)...



Key Points:
Measurements and Comparison:

- Channel CE: Mean = .44, SD = .008
- Nucor SR CE: Mean = .22, SD = .004
- Cliffs SR CE: Mean = .17, SD = .009

Interpretation:

1. The difference in CE impacts weld quality.
 - a. Nucor Side Rail CE is closer to Gerdau Channel CE, so welds will be better.
 - b. Cliffs Side Rail CE is Lower, and so further away from Gerdau Channel CE, so welds would be worse

Conclusions:

1. Reduce Channel CE if possible.
2. Use Side Rail closer to Channel CE, avoid lower CE Side Rail if possible.

Product	Process	Equipment
Material type	Resistance	Weld tips
Material Chemistry	Amps	Transformers
Material Source	Setting Adjustments	Secondary Cables
	Weld failure locations	Weld Controllers


Heat: $Q = i^2 \times R \times t$

- *Very weld time*
 - Low (12 cycles), high (18 cycles)
- *Introduce a material heat-up (ramp) period*
 - Low (no ramp), high (10 cycle ramp)
- *Vary the 2 side rail materials*
 - Low (Nucor), high (Cliffs)

Factor	Factor Name	Level 1 Low(-)	Level 2 High(+)
1	Weld Time	12	18
2	Pre Heat	0	10
3	Material	Nucor 12843502	Cliffs 832Z34810

Welding Schedule, settings, tips, components, alignment, maintenance and setup...



		<p>Maintainance "Triggers" when something goes south with a weather- resistant jacket following the following protocol:</p>	
Task	Triggers	1	Reinforce Current
			Current and consistent, if they are within reason, or need adjusting, such as if it is damaged too much, too fast, it's a wear item, related to the number of winds on the way for other considerations
		2	Inspect Joints
			Inspect for "leakage", seams or damage, including any indication of shifting on the outside. Also re-align "Too loose"
		3	Inspect seams and fasteners
			Inspect for loose fasteners, loose, fasten, fasten, fasten
		4	Considerations
			Determine inspection for Joints, contamination, Foreign material
		5	Heed or Broken
			Inspect joints, bolts, seams, anything that should be looked down or removable, check for cracking, movement, seams, anything that is broken or damaged, lack in other joints, gaskets, etc.
		6	Check Water Flow
			Assess water flow and temperature, control if necessary
		7	Check for any Shrinky or
			Check for shrink, movement and regardless of flow and material, determine if there are any signs or obvious or serious. Looking for any possibility that would cause expanding the path of current
		8	Inspect physical Shiftings or changing
			Inspect current movement, any way, look for anything that was have shifted, difficult to move in one position, and control. Talk with the operator, and check if any changes were made to the machine, and correct back to correct settings. Also, check that PM is not of anything different was done, and why.

[illegible]


Process			
Component Feed and Handling by the welder	Slip	Dimensions	Passes / Fail
	Feed by Operator, speed of the welder	Fe, timing	
	Grabbing rollers (upper and lower)	Fe	
Mechanical Set up and alignment	Leveling	Horizontal error	
	Setting	Setting up tape, equipment	
	Alignment	Alignment of equipment, tape	
Testing			
Rip Test	Rip Test weld assessment	Gr / Fp, Sp, Grains	Pass / Fail
	Rip Test equipment calibration	Criteria for failure:	
	Rip time, before testing	<ul style="list-style-type: none"> - < 15 sec - < 10 sec - < 5 sec - 5 sec. Worst case 	

...then conducting the DoE, and the outcome:


Trial#	Cum. Count	Weld Tim.		Pre Heat	Material	Rip Weld Failure	12345678								
		1	2				3	4	5	6	7	8			
3	3	12	10		Cliffs 832-24810 (+)			0	1	0	0	0	0	0	0
4	4				Cliffs 832-24810 (+)	2	0	0	0	0	0	0	0	0	0
7	7	18	10		Nucor 12843502 (-)	0	0	0	0	0	0	0	0	0	0
8	8	18	10		Nucor 12843502 (-)	0	0	0	0	0	0	0	0	0	0
3	11	12	10		Cliffs 832-24810 (+)	2	0	0	0	1	0	0	0	0	0
12	12	12	10		Cliffs 832-24810 (+)	0	1	0	0	0	0	0	0	0	0
7	15	18	10		Nucor 12843502 (-)	2	0	0	0	1	1	0	0	0	0
8	16	18	10		Nucor 12843502 (-)	0	0	0	0	0	0	0	0	0	0
12	19	12	10		Cliffs 832-24810 (+)	0	1	0	0	0	0	0	0	0	0
4	20	12	10		Cliffs 832-24810 (+)	6	0	0	1	0	2	0	1	1	1
7	23	18	10		Nucor 12843502 (-)	2	1	0	0	0	0	1	0	1	0
8	24	18	10		Nucor 12843502 (-)	0	0	0	0	0	0	0	0	0	0
3	27	12	10		Cliffs 832-24810 (+)	5	0	0	0	1	0	1	0	0	3
4	28	12	10		Cliffs 832-24810 (+)	1	0	0	0	0	0	0	0	0	1
8	31	18	10		Nucor 12843502 (-)	0	0	0	0	0	0	0	0	0	0
8	32	18	10		Nucor 12843502 (-)	0	0	0	1	0	0	0	0	0	0
3	35	12	10		Cliffs 832-24810 (+)	3	1	0	0	1	0	1	0	1	0
12	36	12	10		Cliffs 832-24810 (+)	2	0	0	1	3	0	0	0	0	1
7	39	18	10		Nucor 12843502 (-)	1	0	0	0	0	0	0	0	0	0
8	40	18	10		Nucor 12843502 (-)				0	3	0	1	0	0	0
						Pre-heat 10									

Results... Applying the DoE settings...

The results of the DoE were atypical, in that the 10 cycle ramp overshadowed the other two variables. A t-Test was applied, to verify significance of the difference in rip weld failures.



KPI Performance



- Several pallets of side rails that were ‘on-hold – deemed unweldable’ were then welded with the new settings. Results are shown below, 100% passed, all material was recovered.

"On-Hold" Side Rail recovery - After DoE Settings applied - This material was rejected as unweldable...										
Part Number	Channel Heat Lot #	Siderail Heat Lot #	Machine #	Parts welded at time of rip	Weld Count	Stage 1 (Front) Sch 10	Stage 1 (Front) Sch 20	Stage 2 (Rear) Sch 10	Stage 2 (Rear) Sch 20	Defective Weld Count Operator
72	6103351	832z34810	A030	304	10920	80	80	83		0
84	6102604	na	A033	1	5289	79	79	80		4
72	6103351	832z34810	A030	404	12195	80	80	83		1
84	6102604	na	A033	203	6021	79	79	81		6
84	6102604	NA	A033	303	6021	79	79	81		5
u84			A030	1	0	76	76	80	0	3
u84			A030	7	119	76	76	80	0	3
U120	6103346	NA	A030	1	280	76	76	80		0

- Once all welders are aligned with new alignment tool, in both X & Y Axis, this should drop further.

The Results...

- Reduced from 25% baseline uprite rework to sustainable 3% or less
- Total Cost & lost sales Avoidance for remainder of 2023: \$1.08M
- Improved On-Time Delivery over 25%
- Annualized Savings of \$2.4M



Here's an inspiring case study that underscores the undeniable impact the Six Sigma methodology can have when paired with i3 Consulting's expertise.


In a world where efficiency and cost-effectiveness reign supreme, it is imperative to seize opportunities for savings and improvement. Our recent Six Sigma project, conducted in collaboration with an esteemed manufacturing client, not only showcases our commitment to excellence but also presents a compelling testament to what can be achieved when the right expertise meets a well-defined challenge.

This case study reveals that we helped our client save a staggering \$1.08 million through a meticulously executed Six Sigma project. Now, you might be wondering how this could apply to your organization. The answer is simple: i3 Consulting stands ready to guide you on a similar journey towards success. We bring proven expertise in Six Sigma methodology, a track record of delivering tangible results, and a commitment to partnering with you every step of the way.

Our call to action for you today is this: seize the opportunity to transform your organization. Let's embark on a journey together, where data-driven decisions and process excellence become the pillars of your success. Imagine the possibilities when you harness the power of Six Sigma with i3 Consulting's guidance. Together, we can unlock savings, enhance efficiency, and propel your organization to new heights.

Don't miss out on the chance to achieve remarkable results, just as we have with our esteemed client. Contact us today, and let's begin shaping your own success story—one where substantial savings, operational excellence, and increased customer satisfaction are not just dreams but a tangible reality.

Thank you for your attention, and we look forward to partnering with you on your journey to excellence!



identify | innovate | implement

Email: info@i-3consulting.com

Phone: 307-316-4656

www.i-3consulting.com



SCAN ME